



TOP VIEW OF LID

NO SCALE




TOP VIEW OF BOX

NO SCAN




END VIEW OF LID

NO SCAL




END VIEW OF BOX

SIDE, "A



CUTTING DIAGRAMS FOR 24 GA. GALVANIZED STEEL PANS

NO SCALP




PAN CORNER
DETAIL

BEND TAB
FLAT & SOLDER

CUTTING DIAGRAM

CUTTING DIAGRAM


NO SCALE



SIDE VIEW, COMPLETE UNIT

NOTES

1. PAINT INSIDE WHITE.
2. PAINT OUTSIDE BLACK.
3. SEAL ALL CRACKS.
4. PLACE IN PROTECTED PLACE ON SOUTH SIDE OF A BUILDING.
5. REMOVE WAX AND HONEY WHEN MOST COMBS ARE MELTED. THE HONEY SHOULD BE DISCARDED.



BASED ON: PENN STATE UNIV.
PLAN NO. 790-301

